


Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Dr. Bashir Kh Patient file#: 11457 Date 21/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 43.6 K2 44 K1 Axis 173
- Intra-op full corneal thickness (microns) 531 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.5
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL


- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : _____
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 71487
- Blade Lot # or Single-Use Lot # : 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No 	If yes, what was the flap thickness in microns? <ul style="list-style-type: none"> ❖ Pre-op full corneal thickness <u>531</u> ❖ Residual stromal bed thickness <u>463</u> ❖ Calculated Flap thickness <u>68</u>
---	--

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Dr. Baslaikh Patient file#: 14457 Date 21/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 43.8 K2 44 K1 Axis 26.4
- Intra-op full corneal thickness (microns) 532 ☐ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.4
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : _____
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☐ 1 or ☒ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487
- Blade Lot # or Single-Use Lot # : 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No


2. Potential intra-operative events

- Pseudo Button-hole ☐ Yes ☒ No
- Unacceptable thickness ☒ Yes ☐ No
- Button-hole ☐ Yes ☐ No
- Partial flap ☐ Yes ☐ No
- Free cap ☐ Yes ☐ No
- Decentred Flap ☐ Yes ☐ No
- Stromal Incursion ☐ Yes ☐ No
- Epithelium patch ☐ Yes ☐ No

If yes, what was the flap thickness in microns?

- ❖ Pre-op full corneal thickness 532
- ❖ Residual stromal bed thickness 452
- ❖ Calculated Flap thickness 70

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Dr. Beshikh Patient file#: 14268 Date 14/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 42.6 K2 44.3 K1 Axis 6.3
- Intra-op full corneal thickness (microns) 562 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.9
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : _____
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487
- Blade Lot # or Single-Use Lot # : 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)


C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events
 - Pseudo Button-hole ☐ Yes ☐ No
 - Unacceptable thickness ☒ Yes ☐ No
 - Button-hole ☐ Yes ☐ No
 - Partial flap ☐ Yes ☐ No
 - Free cap ☐ Yes ☐ No
 - Decentred Flap ☐ Yes ☐ No
 - Stromal Incursion ☐ Yes ☐ No
 - Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

If yes, what was the flap thickness in microns?

- ❖ Pre-op full corneal thickness 562
- ❖ Residual stromal bed thickness 496
- ❖ Calculated Flap thickness 76

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Dr. Basleith Patient file#: 144 68 Date 14/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☒ OS
- Keratometries K1 42.6 K2 44.8 K1 Axis 175
- Intra-op full corneal thickness (microns) 558 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.6
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : _____
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☐ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☐ 1 or ☒ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J 1487
- Blade Lot # or Single-Use Lot # : 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- | | |
|---|---|
| <ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No | <p>If yes, what was the flap thickness in microns? _____</p> <ul style="list-style-type: none"> ❖ Pre-op full corneal thickness <u>558</u> ❖ Residual stromal bed thickness <u>490</u> ❖ Calculated Flap thickness <u>68</u> |
|---|---|

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Bashir Kh Patient file#: 14361 Date 14/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 43 K2 5.2 K1 Axis 3.3
- Intra-op full corneal thickness (microns) 527 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.8
- Ametropic correction? ☐ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : _____
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1487
- Blade Lot # or Single-Use Lot # : 1144112
- Moria sterile tubing Reference 19138 Batch number : 8143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- | | |
|--|---|
| <ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If yes, what was the flap thickness in microns?
❖ Pre-op full corneal thickness <u>527</u>
❖ Residual stromal bed thickness <u>443</u>
❖ Calculated Flap thickness <u>84</u> |
|--|---|

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Dr. Baskerville Patient file#: 14361 Date 14/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 43 K2 44.4 K1 Axis 172.5
- Intra-op full corneal thickness (microns) 533 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.8
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL


- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☐ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☐ 1 or ☒ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487
- Blade Lot # or Single-Use Lot # : 1124112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No 	If yes, what was the flap thickness in microns? ♦ Pre-op full corneal thickness <u>533</u> ♦ Residual stromal bed thickness <u>463</u> ♦ Calculated Flap thickness <u>70</u>
---	---

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Dr. Basheikh Patient file#: 14628 Date 21/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 41.5 K2 41.9 K1 Axis 115
- Intra-op full corneal thickness (microns) 548 ☐ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.00
- Ametropic correction? ☐ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL


- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 21487
- Blade Lot # or Single-Use Lot # : 1124112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No 	If yes, what was the flap thickness in microns? _____ ❖ Pre-op full corneal thickness <u>548</u> ❖ Residual stromal bed thickness <u>477</u> ❖ Calculated Flap thickness <u>71</u>
---	---

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: _____ Patient file# : _____ Date _____

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 42.2 K2 42.3 K1 Axis 5
- Intra-op full corneal thickness (microns) 563 ☐ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.00
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL


- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☐ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J 1487
- Blade Lot # or Single-Use Lot # : 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No 	If yes, what was the flap thickness in microns? <ul style="list-style-type: none"> ❖ Pre-op full corneal thickness <u>563</u> ❖ Residual stromal bed thickness <u>481</u> ❖ Calculated Flap thickness <u>82</u>
--	--

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: AHMED HANSEN Patient file#: 14568 Date 17/06/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 42.0 K2 43.2 K1 Axis 23-1
- Intra-op full corneal thickness (microns) 507 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.1mm Pentacam HR
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1487 SBK
- Blade Lot # or Single-Use Lot # : SINGLE USE LOT: 1144112
- Moria sterile tubing Reference 19138 Batch number : 3148602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


1. Characteristics of suction and automated translation:


- Was suction time longer or shorter than usual? If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- | | |
|---|---|
| <ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No | If yes, what was the flap thickness in microns?
✦ Pre-op full corneal thickness <u>507</u>
✦ Residual stromal bed thickness <u>437</u>
✦ Calculated Flap thickness <u>70</u> |
|---|---|

Draw the location of the partial flap or of the pseudo or "see-through" button-hole



Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: ahmed HASSAN Patient file#: 14168 Date 12/06/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 41.8 K2 43.4 K1 Axis 162.0
- Intra-op full corneal thickness (microns) 528 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.1 mm DETECTAcam HL
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1487 SBK
- Blade Lot # or Single-Use Lot # : SING LE USE LOT: 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- | | |
|---|---|
| <ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No | If yes, what was the flap thickness in microns?
✧ Pre-op full corneal thickness <u>528</u>
✧ Residual stromal bed thickness <u>448</u>
✧ Calculated Flap thickness <u>80</u> |
|---|---|

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Ahmed Hussein

Patient file# : 14501

Date 15/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 44.2 K2 45 K1 Axis 3.2
- Intra-op full corneal thickness (microns) 595 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.2 Pentacam HR
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☐ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☐ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 31487 SBK
- Blade Lot # or Single-Use Lot # : Single use LOT: 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? 1 eye
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
- Unacceptable thickness ☒ Yes ☐ No ☒ Pre-op full corneal thickness 595
- Button-hole ☐ Yes ☐ No ☒ Residual stromal bed thickness 514
- Partial flap ☐ Yes ☐ No ☒ Calculated Flap thickness 81
- Free cap ☐ Yes ☐ No
- Decentred Flap ☐ Yes ☐ No
- Stromal Incursion ☐ Yes ☐ No
- Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole



Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Ahmed Hussein Patient file#: 14501 Date 15/6/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

1. Eye ☐ OD ☒ OS
2. Keratometries K1 43.7 K2 45.7 K1 Axis 171.3
3. Intra-op full corneal thickness (microns) 598 ☐ Ultrasound ☐ Imaging ☐ Scheimpflug camera
4. White-to-White (mm) 12.3
5. Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
6. Additional comments on the patient's eye _____

B) MATERIAL

1. Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
2. Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
3. Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
4. Handpiece serial number : 51487
5. Blade Lot # or Single-Use Lot # : Single use 1144112
6. Moria sterile tubing Reference 19138 Batch number : 3143602
7. On approximately how many eyes this specific set had been used before this complication? 2
8. Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- 10 Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
11. New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

1. Characteristics of suction and automated translation:


- Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
- Unacceptable thickness ☒ Yes ☐ No ❖ Pre-op full corneal thickness 596
- Button-hole ☐ Yes ☐ No ❖ Residual stromal bed thickness 522
- Partial flap ☐ Yes ☐ No ❖ Calculated Flap thickness 74
- Free cap ☐ Yes ☐ No
- Decentred Flap ☐ Yes ☐ No
- Stromal Incursion ☐ Yes ☐ No
- Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole



Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Ali Hamed Hussein Patient file#: 14540 Date 10/06/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 42.9 K2 43.4 K1 Axis 26.9
- Intra-op full corneal thickness (microns) 627 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.5 Pentacam HR
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☐ Evo3E ☐ Other Serial Number : 2113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 CBK
- Blade Lot # or Single-Use Lot # : SINGLE USE LOT: 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)


C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events
 - Pseudo Button-hole ☐ Yes ☒ No
 - Unacceptable thickness ☒ Yes ☐ No
 - Button-hole ☐ Yes ☐ No
 - Partial flap ☐ Yes ☐ No
 - Free cap ☐ Yes ☐ No
 - Decentred Flap ☐ Yes ☐ No
 - Stromal Incursion ☐ Yes ☐ No
 - Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

If yes, what was the flap thickness in microns?

- ❖ Pre-op full corneal thickness 627
- ❖ Residual stromal bed thickness 539
- ❖ Calculated Flap thickness 88

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Catherine Busceta Patient file#: 14570 Date 10/06/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 43.0 K2 43.3 K1 Axis 2.6
- Intra-op full corneal thickness (microns) 620 ☐ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.4mm Pentacam HL
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☐ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☐ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 SDC
- Blade Lot # or Single-Use Lot # : SM266 WE LOT : 1144 112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS



1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- | | |
|--|---|
| <ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No | If yes, what was the flap thickness in microns? _____
❖ Pre-op full corneal thickness <u>620</u>
❖ Residual stromal bed thickness <u>551</u>
❖ Calculated Flap thickness <u>69</u> |
|--|---|

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Alfred Thissen Patient file#: 14508 Date 10/06/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT



- Eye ☒ OD ☐ OS
- Keratometries K1 42.1 K2 42.6 K1 Axis 8.1
- Intra-op full corneal thickness (microns) 533 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.3 Pentacam HR
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 31487 SPK
- Blade Lot # or Single-Use Lot # : SINGLE USE LOT : 114412
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
 - Potential intra-operative events
 - Pseudo Button-hole ☐ Yes ☒ No If yes, what was the flap thickness in microns? _____
 - Unacceptable thickness ☒ Yes ☐ No ☒ Pre-op full corneal thickness 533
 - Button-hole ☐ Yes ☐ No ☒ Residual stromal bed thickness 468
 - Partial flap ☐ Yes ☐ No ☒ Calculated Flap thickness 65
 - Free cap ☐ Yes ☐ No
 - Decentred Flap ☐ Yes ☐ No
 - Stromal Incursion ☐ Yes ☐ No
 - Epithelium patch ☐ Yes ☐ No
- Draw the location of the partial flap or of the pseudo or "see-through" button-hole

	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Ali Husein Patient file#: 14508 Date 10/06/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 42.4 K2 42.5 K1 Axis 157.4
- Intra-op full corneal thickness (microns) 558 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.1 Pentacam HR
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1487 SOK
- Blade Lot # or Single-Use Lot # : SINGLE USE LOT: 114411
- Moria sterile tubing Reference 19138 Batch number : 3143 602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)



C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events
 - Pseudo Button-hole ☐ Yes ☒ No
 - Unacceptable thickness ☒ Yes ☐ No
 - Button-hole ☐ Yes ☒ No
 - Partial flap ☐ Yes ☒ No
 - Free cap ☐ Yes ☒ No
 - Decentred Flap ☐ Yes ☒ No
 - Stromal Incursion ☐ Yes ☒ No
 - Epithelium patch ☐ Yes ☒ No

If yes, what was the flap thickness in microns?

- ❖ Pre-op full corneal thickness 558
- ❖ Residual stromal bed thickness 1474
- ❖ Calculated Flap thickness 84

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14577 Date: _____

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 42.6 K2 43.2 K1 Axis 162.5
- Intra-op full corneal thickness (microns) 560 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.6 mm Rentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL


- Console ☐ Evo2 ☐ Evo3 ☐ Evo3E ☐ Other Serial Number : 8117
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☐ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 SBK
- Blade Lot # or Single-Use Lot # : Single use lot 144112
- Moria sterile tubing Reference 19138 Batch number : 314 3602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☐ 0 ☒ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No 	If yes, what was the flap thickness in microns? _____ ✦ Pre-op full corneal thickness <u>560</u> ✦ Residual stromal bed thickness <u>493</u> ✦ Calculated Flap thickness <u>73</u>
--	---

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: CHMED Hussein Patient file#: 14516 Date 10/06/2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 42.0 K2 42.4 K1 Axis 23.0
- Intra-op full corneal thickness (microns) 573 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.9 Pentacam HR
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____


B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 813
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1427 SOK
- Blade Lot # or Single-Use Lot # : 51766 USE LOT: 1144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events
 - Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
 - Unacceptable thickness ☒ Yes ☐ No ☒ Pre-op full corneal thickness 573
 - Button-hole ☐ Yes ☐ No ☒ Residual stromal bed thickness 499
 - Partial flap ☐ Yes ☐ No ☒ Calculated Flap thickness 74
 - Free cap ☐ Yes ☐ No
 - Decentred Flap ☐ Yes ☐ No
 - Stromal Incursion ☐ Yes ☐ No
 - Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: CHMED HUSSEIN Patient file# : _____ Date _____

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☐ OS
- Keratometries K1 _____ K2 _____ K1 Axis _____
- Intra-op full corneal thickness (microns) _____ ☐ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) _____ PENTACAM HR
- Ametropic correction? ☐ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL



- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-K™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☐ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1457 SBK
- Blade Lot # or Single-Use Lot # : SINGLE USE LOT: 114412
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? 50 If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No 	If yes, what was the flap thickness in microns? _____ ❖ Pre-op full corneal thickness <u>580</u> ❖ Residual stromal bed thickness <u>497</u> ❖ Calculated Flap thickness <u>74</u>
---	---

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14603 Date 16 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 41.9 K2 43.8 K1 Axis 176.6
- Intra-op full corneal thickness (microns) 562 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.0mm Pentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 SBK
- Blade Lot # or Single-Use Lot # : single use lot 144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- | | |
|---|---|
| <ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No | If yes, what was the flap thickness in microns?
✦ Pre-op full corneal thickness <u>562</u>
✦ Residual stromal bed thickness <u>478</u>
✦ Calculated Flap thickness <u>84</u> |
|---|---|

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14560 Date 17 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 41.4 K2 42.9 K1 Axis 7.3
- Intra-op full corneal thickness (microns) 546 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.9 mm Pentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☐ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 SPK
- Blade Lot # or Single-Use Lot # : Single use LOT 144112
- Moria sterile tubing Reference 19138 Batch number : 314 3602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
- Unacceptable thickness ☒ Yes ☐ No ☒ Pre-op full corneal thickness 546
- Button-hole ☐ Yes ☐ No ☒ Residual stromal bed thickness 476
- Partial flap ☐ Yes ☐ No ☒ Calculated Flap thickness 70
- Free cap ☐ Yes ☐ No
- Decentred Flap ☐ Yes ☐ No
- Stromal Incursion ☐ Yes ☐ No
- Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14560 Date 17 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 41.0 K2 42.6 K1 Axis 156.9
- Intra-op full corneal thickness (microns) 563 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.1mm Pentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____


B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 11487 SBK
- Blade Lot # or Single-Use Lot # : Single use LOT 144112
- Moria sterile tubing Reference 19138 Batch number : 314 3602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events
 - Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
 - Unacceptable thickness ☒ Yes ☐ No ☒ Pre-op full corneal thickness 563
 - Button-hole ☐ Yes ☐ No ☒ Residual stromal bed thickness 480
 - Partial flap ☐ Yes ☐ No ☒ Calculated Flap thickness 83
 - Free cap ☐ Yes ☐ No
 - Decentred Flap ☐ Yes ☐ No
 - Stromal Incursion ☐ Yes ☐ No
 - Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Dr. Ahmad Hussein Patient file#: 14578 Date 18 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 40.7 K2 41.0 K1 Axis 0.1
- Intra-op full corneal thickness (microns) 588 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.6mm Pentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8117
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 SBK
- Blade Lot # or Single-Use Lot # : Single use LOT 144112
- Moria sterile tubing Reference 19138 Batch number : 314 3602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)



C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? NO If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
- Unacceptable thickness ☒ Yes ☐ No ♦ Pre-op full corneal thickness 588
- Button-hole ☐ Yes ☐ No ♦ Residual stromal bed thickness 500
- Partial flap ☐ Yes ☐ No ♦ Calculated Flap thickness 88
- Free cap ☐ Yes ☐ No
- Decentred Flap ☐ Yes ☐ No
- Stromal Incursion ☐ Yes ☐ No
- Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14578 Date 18 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 41.0 K2 41.2 K1 Axis 32.7
- Intra-op full corneal thickness (microns) 596 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 11.8mm Pentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1487 SBK
- Blade Lot # or Single-Use Lot # : single use LOT 144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☐ -1 ☒ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? NO If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
- Unacceptable thickness ☒ Yes ☐ No ♦ Pre-op full corneal thickness 596
- Button-hole ☐ Yes ☐ No ♦ Residual stromal bed thickness 514
- Partial flap ☐ Yes ☐ No ♦ Calculated Flap thickness 82
- Free cap ☐ Yes ☐ No
- Decentred Flap ☐ Yes ☐ No
- Stromal Incursion ☐ Yes ☐ No
- Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14601 Date 16 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☐ OS
- Keratometries K1 42.2 K2 42.6 K1 Axis 15.0
- Intra-op full corneal thickness (microns) 547 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.4mm Rentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL


- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 SBK
- Blade Lot # or Single-Use Lot # : single use lot 14412
- Moria sterile tubing Reference 19138 Batch number : 314 3602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? NO If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No 	If yes, what was the flap thickness in microns? ❖ Pre-op full corneal thickness <u>547</u> ❖ Residual stromal bed thickness <u>466</u> ❖ Calculated Flap thickness <u>81</u>
---	---

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48 
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14601 Date 16 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 42.4 K2 42.9 K1 Axis 136.4
- Intra-op full corneal thickness (microns) 554 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.3mm pentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL


- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 SBK
- Blade Lot # or Single-Use Lot # : single use LOT 144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- 10 Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? NO If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No 	If yes, what was the flap thickness in microns? <ul style="list-style-type: none"> ❖ Pre-op full corneal thickness <u>554</u> ❖ Residual stromal bed thickness <u>475</u> ❖ Calculated Flap thickness <u>79</u>
---	--

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14610 Date 17 JUNE 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 41.2 K2 41.4 K1 Axis 17.7
- Intra-op full corneal thickness (microns) 581 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.4 mm Reitacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 51487 SBK
- Blade Lot # or Single-Use Lot # : Single use lot 144112
- Moria sterile tubing Reference 19138 Batch number : 314 3602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ 1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS


1. Characteristics of suction and automated translation:

- Was suction time longer or shorter than usual? NO If yes, suction time? _____ sec
- Was the suction good and stable during the pass? ☒ Yes ☐ No
- Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
- Unacceptable thickness ☒ Yes ☐ No ♦ Pre-op full corneal thickness 581
- Button-hole ☐ Yes ☐ No ♦ Residual stromal bed thickness 495
- Partial flap ☐ Yes ☐ No ♦ Calculated Flap thickness 86
- Free cap ☐ Yes ☐ No
- Decentred Flap ☐ Yes ☐ No
- Stromal Incursion ☐ Yes ☐ No
- Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14610 Date 17 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT



- Eye ☐ OD ☒ OS
- Keratometries K1 40.9 K2 41.7 K1 Axis 7.4
- Intra-op full corneal thickness (microns) 586 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.4 mm Pentacam
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☐ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1487 SBK
- Blade Lot # or Single-Use Lot # : Single use Lot. 1144112
- Moria sterile tubing Reference 19138 Batch number : 7147 002
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ 1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☐ 8 ☒ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☒ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? NO If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
 - Potential intra-operative events
 - Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns?
 - Unacceptable thickness ☒ Yes ☐ No ☒ Pre-op full corneal thickness 586
 - Button-hole ☐ Yes ☐ No ☒ Residual stromal bed thickness 514
 - Partial flap ☐ Yes ☐ No ☒ Calculated Flap thickness 72
 - Free cap ☐ Yes ☐ No
 - Decentred Flap ☐ Yes ☐ No
 - Stromal Incursion ☐ Yes ☐ No
 - Epithelium patch ☐ Yes ☐ No
- Draw the location of the partial flap or of the pseudo or "see-through" button-hole

	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14519 Date 14 June 2011

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☒ OD ☐ OS
- Keratometries K1 39.6 K2 41.2 K1 Axis 179.6
- Intra-op full corneal thickness (microns) 564 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.3 mm calliper
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL


- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptor s/n _____ Speed selection ☐ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : J1487 SBK
- Blade Lot # or Single-Use Lot # : single use LOT 144112
- Moria sterile tubing Reference 19138 Batch number : 3143602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☒ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? no If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No
- Potential intra-operative events

<ul style="list-style-type: none"> Pseudo Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Unacceptable thickness <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Button-hole <input type="checkbox"/> Yes <input type="checkbox"/> No Partial flap <input type="checkbox"/> Yes <input type="checkbox"/> No Free cap <input type="checkbox"/> Yes <input type="checkbox"/> No Decentred Flap <input type="checkbox"/> Yes <input type="checkbox"/> No Stromal Incursion <input type="checkbox"/> Yes <input type="checkbox"/> No Epithelium patch <input type="checkbox"/> Yes <input type="checkbox"/> No 	If yes, what was the flap thickness in microns? _____ ❖ Pre-op full corneal thickness <u>564</u> ❖ Residual stromal bed thickness <u>496</u> ❖ Calculated Flap thickness <u>68</u>
---	---

Draw the location of the partial flap or of the pseudo or "see-through" button-hole

Moria	Flap complication report	EAQA018 / C	Approuvé(e) par : Jean Paul MERCEREAU Directeur Assurance Qualité et Affaires réglementaires le 06/07/2011 16:03:48
	Date d'application : 06/07/2011		

Surgeon: Ahmad Hussein Patient file#: 14519 Date 14 June 2015

REPORT OF INTRAOPERATIVE FLAP COMPLICATION

A) PATIENT

- Eye ☐ OD ☒ OS
- Keratometries K1 39.5 K2 41.0 K1 Axis 170.9
- Intra-op full corneal thickness (microns) 581 ☒ Ultrasound ☐ Imaging ☐ Scheimpflug camera
- White-to-White (mm) 12.3 mm Calliper
- Ametropic correction? ☒ Myopic ☐ Hyperopic ☒ Astigmatic
- Additional comments on the patient's eye _____

B) MATERIAL

- Console ☐ Evo2 ☐ Evo3 ☒ Evo3E ☐ Other Serial Number : 8113
- Microkeratome ☐ ONE ☐ ONE Use ☐ CB ☐ CBSU ☐ M2 ☐ M2SU ☒ ONE Use-Plus ☐ EPI-k™
☐ Evo2 Speed adaptator s/n _____ Speed selection ☒ 1 or ☐ 2 (For M2/M2SU and One Use Plus only)
- Microkeratome metal head ☐ 150 ☐ 130 ☐ 110 ☐ 90 Serial Number: _____
- Handpiece serial number : 11487 SBK
- Blade Lot # or Single-Use Lot # : Single use LOT 144112
- Moria sterile tubing Reference 19138 Batch number : 314 3602
- On approximately how many eyes this specific set had been used before this complication? _____
- Ring ☐ Disposable ☐ Single use ☐ H ☒ -1 ☐ 0 ☐ +1 ☐ +2 ☐ +3 ☐ -1 LC
- Stop ☐ 7 ☐ 7.5 ☒ 8 ☐ 8.5 ☐ 8.75 ☐ 9 ☐ Other _____
- New blade? ☐ Yes ☐ No (Check "No" for the second eye in bilateral simultaneous LASIK)

C) INTRA-OPERATIVE RESULTS

- Characteristics of suction and automated translation:
 - Was suction time longer or shorter than usual? No If yes, suction time? _____ sec
 - Was the suction good and stable during the pass? ☒ Yes ☐ No
 - Was the forward movement smooth and regular? ☒ Yes ☐ No

2. Potential intra-operative events

- Pseudo Button-hole ☐ Yes ☐ No If yes, what was the flap thickness in microns? _____
- Unacceptable thickness ☒ Yes ☐ No ❖ Pre-op full corneal thickness 581
- Button-hole ☐ Yes ☐ No ❖ Residual stromal bed thickness 500
- Partial flap ☐ Yes ☐ No ❖ Calculated Flap thickness 81
- Free cap ☐ Yes ☐ No
- Decentred Flap ☐ Yes ☐ No
- Stromal Incursion ☐ Yes ☐ No
- Epithelium patch ☐ Yes ☐ No

Draw the location of the partial flap or of the pseudo or "see-through" button-hole